

Problem: Safety film on balustrades was deteriorated and needed replacing. The views needed to stay unrestricted.

Solution: Strip existing film and install Armorgard™ C90 100 micron clear Safety Film to maintain the safety levels in each unit.



- Total Area = approximately 1000m²
- 16 levels each with 12 units.
- Installation was done in stages over a 12 month period as the resort had to keep trading whilst the refurbishment was taking place. Each floor was vacated one at a time.
- Works were to be co-ordinated with the builder as each floor was vacant for only a very short period.
- The balustrades were on balconies and therefore an external application. Early morning starts were essential to avoid problems with the wind.
- Periods of rain and windy weather slowed down the installation process but the strict deadlines were always met.

TO
CO
WE
SU
RO
PR
P

Licensed Applicators For



33 Navigator Place HENDRA QLD 4011
PO Box 1116 TOOMBUL QLD 4012
Phone: 07 3268 8444 Fax: 07 3268 8484
E-mail: email@cooltone.com.au
Website: www.cooltone.com.au

